


# SAFETY RECALL

## SRAM PowerLock® Bike Chain Connector

PowerLocks® with date codes M or N can break and cause the chain to detach.



PowerLock® connectors were sold:

- 1.) By themselves from January 2009 through August 2009.
- 2.) With SRAM 10-speed bike chains (PC-1030, -1050, -1070, -1090, and -1090R) from January 2009 through August 2009.
- 3.) As original equipment on some Guru, Surly, Salsa, BMC, Serotta, Seven, & Ridley brand bikes from April 2009 through August 2009.

If your bike has an affected SRAM PowerLock®, stop riding it immediately and return the PowerLock® to a SRAM dealer for a free replacement.  
For more information or for assistance, contact SRAM at

**(800) 346-2928**